Method of Treating Oil and Gas Wells" by Jeffery M. Wilkinson Serial. No. 10/826,783 Filed 04/16/04 Page 1 of 4 100-150 人 Zone 1 (Lowest Stress) 120 160 人 Zone 2 130 110 (Intermediate Stress) 170 人 Zone 3 140 (Highest Stress)

FIG. 1

 \oplus




FIG. 2

